

To: Anfrew Shipman

Fax: 401-8244

From: David G. Marwell

Date: April 20, 2017

Pages: 1, including cover sheet.

Andrew:

The FSS proposal looks good. I do, however, have several questions:

Card Readers

Will the Card Readers be compatible with the system used elsewhere in the building? In the stairways?

Electrical Work

Is this work necessary? Are there not sufficient outlets and grounds in the Telephone/LAN Room (2613)? If not why not?

What is the story on the conduit to the guard's desk? Is it necessary? FSS suggests that it is advisable? Why? What are the risks?

Are the qualifications listed on Page 2 of Ogden's letter reasonable? Do they justify the same mark-up as the other work?

fax

From the desk of
David G. Marwell
Executive Director
Assassination Records Review Board
600 E Street NW
Washington, DC 20530

(202) 724-0088
Fax: (202) 724-0457